

King Street Tile Drain Inspections

Inspection Report for Observation:
AgriculturalFlooding1

Location: Right

Photo 1 Direction: South

Comments:

Existing flooding in farm field right side of the drain. Picture facing South.

Observation Location:




Photo 1



CLIENT	Saginaw County Public Works Commissioner	 HUBBELL, ROTH & CLARK, INC CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 http://www.hrc-engr.com	DATE:	08/16/2016
				SCALE:	
NOTE			SHEET #:		
			JOB #:	20160331	

King Street Tile Drain Inspections

Inspection Report for Observation:
AgriculturalFlooding2

Location: Right

Photo 1 Direction: East

Comments:

Considerable flooding in farm field right side of the drain. Picture facing East

Observation Location:




Photo 1



CLIENT	Saginaw County Public Works Commissioner	 HUBBELL, ROTH & CLARK, INC CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 http://www.hrc-engr.com	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

King Street Tile Drain Inspections

Inspection Report for Observation:
AgriculturalFlooding3

Location: Right

Photo 1 Direction: Southeast

Comments:

Flooding on edge of farm field right side of the drain . Picture facing Southeast

Observation Location:




Photo 1



CLIENT	Saginaw County Public Works Commissioner	 HUBBELL, ROTH & CLARK, INC CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 http://www.hrc-engr.com	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

King Street Tile Drain Inspections

Inspection Report for Observation:
AgriculturalFlooding4

Location: Right

Photo 1 Direction: South

Comments:

Flooded woods 50' south of the drain. Right side of the drain. Picture facing South.

Observation Location:




Photo 1

CLIENT	Saginaw County Public Works Commissioner	 HUBBELL, ROTH & CLARK, INC CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 http://www.hrc-engr.com	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

King Street Tile Drain Inspections

Inspection Report for Observation:
AgriculturalFlooding5

Location: Right

Photo 1 Direction: East

Comments:

Agricultural flooding on the east side of the drain can be seen in dry conditions where farmland isn't growing. Picture facing east from outside of drain.

Observation Location:




Photo 1



CLIENT	Saginaw County Public Works Commissioner	 HUBBELL, ROTH & CLARK, INC CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 http://www.hrc-engr.com	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

King Street Tile Drain Inspections

Inspection Report for Observation:
AgriculturalFlooding6

Location: Left

Photo 1 Direction: East

Comments:

Some agricultural flooding on left side of drain facing upstream. Picture facing east.

Observation Location:




Photo 1



CLIENT	Saginaw County Public Works Commissioner	 HUBBELL, ROTH & CLARK, INC CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 http://www.hrc-engr.com	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

King Street Tile Drain Inspections

Inspection Report for Observation:
AgriculturalFlooding7

Location: Left

Photo 1 Direction: North

Comments:

Agricultural flooding on left side of drain facing upstream. It spans about 100' out and 50' wide. Picture facing north from atop the drain crossing.

Observation Location:




Photo 1



CLIENT	Saginaw County Public Works Commissioner	 HUBBELL, ROTH & CLARK, INC CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 http://www.hrc-engr.com	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

King Street Tile Drain Inspections

Inspection Report for Observation:
AgriculturalFlooding8

Location: Left

Photo 1 Direction: North

Comments:

Agricultural flooding on left side of drain facing upstream. It extends from drain approximately 50' and is 15' wide. Picture facing north from drain.

Observation Location:




Photo 1



CLIENT	Saginaw County Public Works Commissioner	 HUBBELL, ROTH & CLARK, INC CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 http://www.hrc-engr.com	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

King Street Tile Drain Inspections

Inspection Report for Observation:
AgriculturalFlooding9

Location: Left

Photo 1 Direction: East

Comments:

Agricultural flooding on left side of drain facing upstream. Water is about 100' east of the drain and area is 40'x40'. Picture facing east from bend in drain.

Observation Location:




Photo 1



CLIENT	Saginaw County Public Works Commissioner	 HUBBELL, ROTH & CLARK, INC CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 http://www.hrc-engr.com	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

King Street Tile Drain Inspections

Inspection Report for Observation:
AgriculturalFlooding10

Location: Left

Photo 1 Direction: East

Comments:

Agricultural flooding on left side of drain facing upstream. Water is approximately 50' east of drain and is 60'x25' in size. Picture facing east from drain.

Observation Location:




Photo 1



CLIENT	Saginaw County Public Works Commissioner	 HUBBELL, ROTH & CLARK, INC CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 http://www.hrc-engr.com	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

King Street Tile Drain Inspections

Inspection Report for Observation:
AgriculturalFlooding11

Location: Left

Photo 1 Direction: Northeast

Comments:

Two agricultural flooding ponds to the northeast of the drain. Near one is 35' away and far one is 50' past it. Near one is 20'x40' and far one is 20'x20'. Picture facing northeast away from drain.

Observation Location:




Photo 1



CLIENT	Saginaw County Public Works Commissioner	 HUBBELL, ROTH & CLARK, INC CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 http://www.hrc-engr.com	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331