

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**BridgeCrossing1**

**Structure Type:** Wood Bridge

**Structure Condition:** Poor

**Entrance/Exit Type:** Concrete Headwall

**Photo 1 Direction:**


**Downstream Comments:**

(Footbridge) Photo 2 ds 30 ft bridge right side

**Upstream Comments:**

Photo 1 Right side wood bridge with steel support, photo 3 missing plank on bridge

**Observation Location:**



**Photo 1**



**Photo 2**



**Photo 3**



CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**BridgeCrossing2**

**Structure Type:** Wood Bridge

**Structure Condition:** Fair

**Entrance/Exit Type:** Concrete Headwall

**Photo 1 Direction:**


**Downstream Comments:**

(Footbridge) Photo 3 taken facing downstream from other side of bridge.

**Upstream Comments:**

Wood bridge with holes. Photo 1 taken facing north. Photo 2 taken facing upstream.

**Observation Location:**



**Photo 1**



**Photo 2**



**Photo 3**



CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331


# King Street Tile Drain Inspections

Inspection Report for Observation:  
**BridgeCrossing3**

**Structure Type:** CMPA  
**Structure Condition:** Good  
**Entrance/Exit Type:** Other  
**Photo 1 Direction:**  
**Downstream Comments:**  
 Downstream left side photo 2

**Upstream Comments:**  
 Upstream right side photo 1, half CMPA

**Observation Location:**



**Photo 1**



**Photo 2**



**Photo 3**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**BridgeCrossing4**

**Structure Type:** Concrete Box

**Structure Condition:** Good

**Entrance/Exit Type:** Concrete Headwall

**Photo 1 Direction:**


**Downstream Comments:**

(M-13 Bridge) Photo taken on east side of m-13 facing west photo 2

**Upstream Comments:**

Photo taken on west side of m-13 facing east photo 1.

**Observation Location:**



**Photo 1**



**Photo 2**



**Photo 3**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**BridgeCrossing5**

**Structure Type:** Steel Truss Bridge

**Structure Condition:** Fair

**Entrance/Exit Type:**

**Photo 1 Direction:**


**Downstream Comments:**

Railroad bridge. Vegetation, woody debris, bank erosion, and sediment. Photo1

**Upstream Comments:**

3 large diam stumps under railroad. Sediment, vegetation, and bank erosion. Photo2.

**Observation Location:**



**Photo 1**



**Photo 2**

**Photo 3**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections


Inspection Report for Observation:  
**BridgeCrossing6**

**Structure Type:** Multi-Plate  
**Structure Condition:** Poor  
**Entrance/Exit Type:**  
**Photo 1 Direction:** Facing Upstream

**Downstream Comments:**  
 (Williamson Road Bridge) Bridge crossing under williamson rd. Erosion at both banks and headwall. Bridge in poor condition. Rusted out. Sediment deposits downstream of sop. Sop enters from right side under the bridge.

**Upstream Comments:**  
 Rusted underneath. See photo3. Erosion on both banks and headwall. Rocks and debris in bottom. Enters crossing at 45 deg angle. Excessive vegetation.

**Observation Location:**



**Photo 1**



**Photo 2**



**Photo 3**



CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**BridgeCrossing7**

**Structure Type:** Concrete Bridge

**Structure Condition:** Fair

**Entrance/Exit Type:**

**Photo 1 Direction:**


**Downstream Comments:**

(Footbridge) Small amounts of crumbling at bottom of bridge. Spoke to homeowner. Flooding in grass, sometimes over tops the bridge. Photo1. Foot path on south side of King st. Fence on both sides.

**Upstream Comments:**

Just downstream of King st crossing.

**Observation Location:**



**Photo 1**



**Photo 2**



**Photo 3**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections


Inspection Report for Observation:  
**BridgeCrossing8**

**Structure Type:** Concrete Box  
**Structure Condition:** Good  
**Entrance/Exit Type:** Wingwalls  
**Photo 1 Direction:** Facing Upstream

**Downstream Comments:**  
 (I-75 Bridge) Headwalls in fair condition. Fence just downstream. Sops enter on each side from I75. Heavy vegetation, sediment, and woody debris just downstream of crossing.

**Upstream Comments:**  
 More loose sediment on upstream side. Two hdpe sops from I75 enter on each side. No fence, but currently under construction so might be upcoming. New riprap headwalls.

**Observation Location:**



**Photo 1**



**Photo 2**



**Photo 3**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**BridgeCrossing9**

**Structure Type:** Wood Bridge

**Structure Condition:** Fair

**Entrance/Exit Type:** Concrete Headwall

**Photo 1 Direction:** Facing Upstream


**Downstream Comments:**

(Footbridge north of drain) Woody debris and excessive vegetation overhanging drain. Wood bridge in fair shape. Entrance/exit type wood and concrete blocks. About 32 ft long across drain.

**Upstream Comments:**

Excessive woods debris on upstream end. Erosion on both sides of bank. Photo 3 taken facing north showing entire wood bridge.

**Observation Location:**



**Photo 1**



**Photo 2**



**Photo 3**



CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331