

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet1**

**Material Type:** Other

**Diameter (inches):** 8

**Condition:** Fair


**Location:** Right Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

Plastic tile on right side upstream. Erosion at outlet. Photo taken facing north.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet2**

**Material Type:** SDR?PVC

**Diameter (inches):** 6

**Condition:** Good


**Location:** Left Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

Left side of drain, PVC 6" diam, photo facing north.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet3**

**Material Type:** Clay

**Diameter (inches):** 3

**Condition:** Fair


**Location:** Right Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

3" clay field tile. Enters drain on right. Photo facing north.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016	
				SCALE:		
NOTE					SHEET #:	
					JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet4**

**Material Type:** Clay

**Diameter (inches):** 2

**Condition:** Fair


**Location:** Right Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

2" clay field tile enters drain from right. Photo facing northeast.

**Observation Location:**



Source: Esri, DigitalGlobe,  
GeoEye, Earthstar  
Geographics, CNES/Airbus  
DS, USDA, USGS, AEX,  
Getmapping, AeroGrid, IGN,

**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet5**

**Material Type:** CMP

**Diameter (inches):** 2

**Condition:** Poor


**Location:** Right Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

2.5" diam field tile outlet. Broken at outlet to drain. Significant erosion. Photo facing northeast. Loose sediment at outlet. Excessive vegetation clump downstream.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**



**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet6**

**Material Type:** Clay

**Diameter (inches):** 2

**Condition:** Poor


**Location:** Right Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

Field tile outlet enters drain on right. Clay, 2.5" diam. Significant erosion at outlet. Photo facing south.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet7**

**Material Type:** Other

**Diameter (inches):** 6

**Condition:** Fair


**Location:** Left Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

Photo facing northeast. 6" metal field tile outlet. Enters drain on left.

**Observation Location:**



**Photo 1**



**Photo 2**

**Photo 3**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet8**

**Material Type:** Clay

**Diameter (inches):** 6

**Condition:** Failed


**Location:** Left Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

Broken field tile. Significant erosion 30 ft inland.

**Observation Location:**



**Photo 1**



**Photo 2**



**Photo 3**



**Photo 4**



CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>		DATE:	08/16/2016
			NOTE		SCALE:	
					JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet9**

**Material Type:** Clay

**Diameter (inches):** 8

**Condition:** Poor


**Location:** Right Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

Field tile outlet on right side is broken 30 ft south of drain. Side drain formed. Photo1 facing south.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**



**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet10**

**Material Type:** CMP

**Diameter (inches):** 10

**Condition:** Failed


**Location:** Right Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

Clay field tile on right side facing upstream. Broken apart in failed condition. CMP extending 20 ft from field. Rusting. Photo 1 taken facing looking down at field tile. Photo 2 facing south.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**



**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet11**

**Material Type:** CMP

**Diameter (inches):** 8

**Condition:** Fair


**Location:** Left Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

8" diam cmp field tile outlet enters drain on left side. Photo facing north.  
Erosion at the outlet. Stretches inland 8 ft.

**Observation Location:**



**Photo 1**



**Photo 2**

**Photo 3**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet12**

**Material Type:** Other

**Diameter (inches):** 6

**Condition:** Fair


**Location:** Right Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

6" green plastic field tile outlet enters drain on right side. Erosion at outlet. Photo facing south.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet13**

**Material Type:** SDR?PVC

**Diameter (inches):** 4

**Condition:** Fair


**Location:** Left Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

4" PVC field tile outlet enters drain on left. Photo1 facing north.

**Observation Location:**



**Photo 1**



**Photo 2**

**Photo 3**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet14**

**Material Type:** Other

**Diameter (inches):** 10

**Condition:** Fair


**Location:** Right Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

Field tile outlet on right side of drain facing upstream. Plastic material. About 10" diameter. Fair condition, little rusty, but no direction to flow into drain. Photo 1 taken facing upstream. Photo 2 taken facing south. Photo 3 taken facing southwest.

**Observation Location:**



**Photo 1**



**Photo 2**



**Photo 3**



**Photo 4**



CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>		DATE:	08/16/2016
			NOTE		SCALE:	
					JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet15**

**Material Type:** Other

**Diameter (inches):** 6

**Condition:** Good


**Location:** Left Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

6" field tile outlet enters drain on left. Grate is plugged. Opposite of additional field tile. Photo facing north.

**Observation Location:**



Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AEX, Getmapping, Aerogrid, IGN,

**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet16**

**Material Type:** Other

**Diameter (inches):** 6

**Condition:** Good


**Location:** Right Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

6" field tile enters drain on right side. Splash pad present but in poor shape. Opposite of additional field tile outlet. Photo facing south.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**



**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet17**

**Material Type:** Other

**Diameter (inches):** 4

**Condition:** Good


**Location:** Right Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

4" field tile outlet enters drain on right side. No splash pad. Erosion at outlet. Photo facing south.

**Observation Location:**



**Photo 1**



**Photo 2**

**Photo 3**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet18**

**Material Type:** Other

**Diameter (inches):** 3

**Condition:** Poor


**Location:** Right Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

3" diam metal field tile outlet enters drain on right. Pipe is rusted. Photo facing south.

**Observation Location:**



**Photo 1**



**Photo 2**

**Photo 3**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet19**

**Material Type:** Other

**Diameter (inches):** 3

**Condition:** Failed


**Location:** Left Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

Failed metal field tile outlet enters drain on left. Erosion around it. Sediment cave in on left side of bank. Photo1 facing northwest.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**



**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet20**

**Material Type:** Other

**Diameter (inches):** 4

**Condition:**


**Location:** Left Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

4" diam failed metal field tile outlet enters drain on left side. Erosion around it. Broken piece 6 ft from drain channel. Photo facing northwest.

**Observation Location:**



**Photo 1**



**Photo 2**

**Photo 3**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet21**

**Material Type:** Other

**Diameter (inches):** 3

**Condition:**


**Location:** Left Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

Failed 3" diam metal field tile outlet on left side of drain. Photo facing northwest.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet22**

**Material Type:** SDR?PVC

**Diameter (inches):** 4

**Condition:** Fair


**Location:** Right Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

4" pvc field tile outlet enters drain on right side. Photo facing southeast.

**Observation Location:**



**Photo 1**



**Photo 2**

**Photo 3**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet23**

**Material Type:** HDPE

**Diameter (inches):** 20

**Condition:** Good


**Location:** Right Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

HDPE field tile on right side of drain. Good condition. Photos taken facing south.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**



**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet24**

**Material Type:** Other

**Diameter (inches):** 10

**Condition:** Good


**Location:** Right Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

Metal field tile. Decent condition. Little rusty. About 10" diameter. Photo taken facing south.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet25**

**Material Type:** SDR?PVC

**Diameter (inches):** 8

**Condition:** Good


**Location:** Right Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

PVC pipe on right side of drain. Good condition, but flow path to drain is not great. Broken concrete below. Photos taken facing south.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**



**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet26**

**Material Type:** Clay

**Diameter (inches):** 6

**Condition:** Good


**Location:** Left Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

Clay 6" field tile on left side facing upstream. Poking thru tree roots.  
Photo taken facing north. Might just be debris, but has erosion around it.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet27**

**Material Type:** Clay

**Diameter (inches):** 4

**Condition:** Poor


**Location:** Right Side Facing Upstream

**Photo 1 Direction:** East

**Comments:**

4" clay field tile right side of the drain . Picture facing East

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet28**

**Material Type:** Concrete

**Diameter (inches):** 4

**Condition:** Failed


**Location:** Left Side Facing Upstream

**Photo 1 Direction:** West

**Comments:**

4 " conc field tile left side of the drain. Picture facing upstream.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet29**

**Material Type:** SDR?PVC

**Diameter (inches):** 4

**Condition:** Good


**Location:** Left Side Facing Upstream

**Photo 1 Direction:** West

**Comments:**

4" pvc field tile left side of the drain. Picture facing east.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet30**

**Material Type:** Concrete

**Diameter (inches):** 4

**Condition:** Poor


**Location:** Right Side Facing Upstream

**Photo 1 Direction:** South

**Comments:**

4" conc field tile right side of the drain. Picture facing south.

**Observation Location:**



**Photo 1**

**Photo 2**

**Photo 3**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
	NOTE				SCALE:
				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet31**

**Material Type:** Concrete

**Diameter (inches):** 4

**Condition:** Poor


**Location:** Right Side Facing Upstream

**Photo 1 Direction:** South

**Comments:**

4" conc field tile right side of the drain. Picture facing south.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet32**

**Material Type:** Other

**Diameter (inches):**

**Condition:** Failed


**Location:** Right Side Facing Upstream

**Photo 1 Direction:** South

**Comments:**

Could not determine pipe material. 6" field tile outlet enters drain on right. Broken segments. Bank erosion inland 20 ft.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet33**

**Material Type:** HDPE

**Diameter (inches):** 4

**Condition:** Good


**Location:** Right Side Facing Upstream

**Photo 1 Direction:** South

**Comments:**

4" hdpe field tile outlet enters drain on right. Next to 12" sop.

**Observation Location:**



Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AEX, Getmapping, Aerogrid, IGN,

**Photo 1**



**Photo 2**

**Photo 3**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet34**

**Material Type:** Clay

**Diameter (inches):** 6


**Condition:** Good

**Location:** Left Side Facing Upstream

**Photo 1 Direction:** Facing Upstream

**Comments:**  
Erosion at the mouth of the pipe. Pipe possibly made of steel.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet35**

**Material Type:** CMP

**Diameter (inches):** 8

**Condition:** Poor


**Location:** Left Side Facing Upstream

**Photo 1 Direction:** Facing Downstream

**Comments:**

Field tile on left side of drain. Rusted with vegetation growing inside. About 8" diameter. Layered with excessive vegetation around drain.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**



**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet36**

**Material Type:** HDPE

**Diameter (inches):** 10

**Condition:** Fair


**Location:** Right Side Facing Upstream

**Photo 1 Direction:** South

**Comments:**

Fair HDPE field tile on right side of drain. Hole on top. About 6" diameter. Not sure if field or surface because of soccer field.

**Observation Location:**



Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AEX, Getmapping, Aerogrid, IGN,

**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet37**

**Material Type:** Clay

**Diameter (inches):** 20

**Condition:** Fair


**Location:** Right Side Facing Upstream

**Photo 1 Direction:** South

**Comments:**

Clay field tile on right side of drain. Fair condition about 20" diameter. Holes on top. Not sure if field or surface outlet because of soccer field.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet38**

**Material Type:** Clay

**Diameter (inches):** 6

**Condition:** Failed


**Location:** Left Side Facing Upstream

**Photo 1 Direction:** Northeast

**Comments:**

Failed field tile on left side of drain. 6" diameter. Broken apart at end.  
Drains into log jam.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet39**

**Material Type:** Clay

**Diameter (inches):** 8

**Condition:** Good


**Location:** Right Side Facing Upstream

**Photo 1 Direction:** South

**Comments:**

Picture facing south from the drain. The field tile is in a hole and doesn't outflow properly.

**Observation Location:**



Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AEX, Getmapping, Aerogrid, IGN,

**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet40**

**Material Type:** Clay

**Diameter (inches):** 4


**Condition:** Poor

**Location:** Left Side Facing Upstream

**Photo 1 Direction:** Northwest

**Comments:**  
4" clay field tile left side of drain. Picture facing North west

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet41**

**Material Type:** Clay

**Diameter (inches):** 4

**Condition:** Poor


**Location:** Left Side Facing Upstream

**Photo 1 Direction:** North

**Comments:**

4" clay field tile left side of the drain under tree. Picture facing north.

**Observation Location:**



**Photo 1**



**Photo 2**

**Photo 3**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet42**

**Material Type:** Clay

**Diameter (inches):** 6

**Condition:** Failed


**Location:** Left Side Facing Upstream

**Photo 1 Direction:** North

**Comments:**

Buried field tile outlet enters drain left side. Broken end segment. Erosion at outlet.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet43**

**Material Type:** Clay

**Diameter (inches):** 6

**Condition:** Poor


**Location:** Left Side Facing Upstream

**Photo 1 Direction:** North

**Comments:**

6" field tile outlet enters drain on left. Loose sediment downstream. Concrete block head wall.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet44**

**Material Type:** CMP

**Diameter (inches):** 4

**Condition:** Fair


**Location:** Left Side Facing Upstream

**Photo 1 Direction:** North

**Comments:**

Field tile on left side of drain. Hidden under excessive overhanging vegetation. 4 in. in fair shape, little rusty. Hard to get picture. Can see an attempt at a splash pad, but is not in use right now.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**



**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
	NOTE				SCALE:
				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet45**

**Material Type:** HDPE

**Diameter (inches):** 4

**Condition:** Poor


**Location:** Right Side Facing Upstream

**Photo 1 Direction:**

**Comments:**

4" diam hdpe field tile outlet enters drain on right. 15 ft right of drain. End piece is cracked. Erosion at outlet. On downstream side of farm crossing.

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**



**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet46**

**Material Type:** SDR?PVC

**Diameter (inches):** 8

**Condition:** Good


**Location:** Left Side Facing Upstream

**Photo 1 Direction:** Northeast

**Comments:**

8" field tile left side under water. Picture facing Northeast

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331

# King Street Tile Drain Inspections

Inspection Report for Observation:  
**FieldTileOutlet47**

**Material Type:** SDR?PVC

**Diameter (inches):** 4

**Condition:** Good

**Location:** Left Side Facing Upstream

**Photo 1 Direction:** East

**Comments:**

4" field tile left side full of water. Picture facing East

**Observation Location:**



**Photo 1**



**Photo 3**

**Photo 2**

**Photo 4**

CLIENT	Saginaw County Public Works Commissioner	 <b>HUBBELL, ROTH &amp; CLARK, INC</b> CONSULTING ENGINEERS SINCE 1915	555 Hulet Drive P.O. Box 824 Bloomfield Hills, MI 48303-0824 (248) 454-6300 <a href="http://www.hrc-engr.com">http://www.hrc-engr.com</a>	DATE:	08/16/2016
				SCALE:	
NOTE				SHEET #:	
				JOB #:	20160331